

Site #: MBR 23 SN: 30 Date: 2/5/24

 EASTING: 395629 NORTHING: 6551604


 nT: _____ LOCAL START TIME: 1720
HH:MM

BATTERY

No Load: 13w/ Solar panel: 13.03

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.1</u>	<u>0.1</u>
DC (mV)	<u>15.1</u>	<u>15.7</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.6</u>	<u>1.3</u>
S	<u>50</u>	<u>0.1</u>	<u>16.6</u>
E	<u>50</u>	<u>0.2</u>	<u>3.8</u>
W	<u>50</u>	<u>0.1</u>	<u>19.5</u>

LOCAL DATE: 06/06/24LOCAL TIME: 1050

DIPOLES	E _x	E _y
kΩ	<u>1.3</u>	<u>1.0</u>
mV _{DC}	<u>14.9</u>	<u>NOT STABLE</u>

BATTERY

No Load: 12.4

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: SEAssistant: CC

Technician: _____

Assistant: _____