


 Site #: MBR 25 SN: _____ Date: 1/5/2024


 EASTING: 468611 NORTHING: 6553812 (251)

 nT: _____ LOCAL START TIME: _____
HH:MM

BATTERY

No Load: 12.9w/ Solar panel: 13.4LEMI: 13.4

DIPOLES	E _x	E _y
Length (m)		
kΩ	<u>0.4</u>	<u>0.2</u>
DC (mV)	<u>10.3</u>	<u>54.3</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.3</u>	24.8
S	<u>50</u>	<u>0.3</u>	35.1
E	<u>50</u>	<u>0.3</u>	51.8
W	<u>50</u>	<u>0.1</u>	2.7

 LOCAL DATE: 05/06/24
 LOCAL TIME: 1505

DIPOLES	E _x	E _y
kΩ	1.0	1.4
mV _{DC}	1.0	60.6

BATTERY

No Load: 14.9

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

No data recorded on 15/05, 22/05, 23/05 - don't believe its related to the battery or charging as there is good data on either side of these dates

 Technician: Shane Assistant: Corey

Technician: _____ Assistant: _____