



Site #: MBR 26 SN: 50 Date: 1/5/2024

EASTING: 495860 NORTHING: 6556259

nT: _____ LOCAL START TIME: 2.30 pm
HH:MM


BATTERY

No Load: 12.95

w/ Solar panel: 13.05

LEMI: 13.35

DIPOLES	E _x	E _y
Length (m)		
kΩ	<u>3.2</u>	<u>0.15</u>
DC (mV)	<u>11.5</u>	<u>16.9</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.1</u>	<u>9.6</u>
S	<u>50</u>	<u>0.15</u>	<u>21.2</u>
E	<u>50</u>	<u>0.15</u>	<u>22.5</u>
W	<u>50</u>	<u>3.1</u>	<u>5.6</u>

Technician: SE

Assistant: CC

LOCAL DATE: 05/06/24

LOCAL TIME: 1305

DIPOLES	E _x	E _y
kΩ	0.16	0.25
mV _{DC}	2.7	3.6

BATTERY

No Load: 13.38

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

At pickup, nT = +123

Technician: _____

Assistant: _____