

Site #: MBS 25 SN: 55 Date: 30/4/2024

 EASTING: 313 967 NORTHING: 6653705


 nT: _____ LOCAL START TIME: _____
HH:MM

BATTERY

No Load: 12.95w/ Solar panel: 13.07 cloudy

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.1</u>	<u>0.1</u>
DC (mV)	<u>1.6</u>	<u>1.6</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.110</u>	<u>4.7</u>
S	<u>50</u>	<u>0.15</u>	<u>6.4</u>
E	<u>50</u>	<u>0.1</u>	<u>5.7</u>
W	<u>50</u>	<u>0.1</u>	<u>4.0</u>

 Technician: SE Assistant: CC
LOCAL DATE: 02/06/24LOCAL TIME: 0925

DIPOLES	Ex	E _y
kΩ	<u>1.0</u>	<u>0.12</u>
mV _{DC}	<u>50.4</u>	<u>0.3</u>

BATTERY

No Load: 13.2

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Data recorder was non responsive ie, couldn't access any of the menus or scroll through to see any of the readings. it stopped recording after 16 days.

Technician: _____ Assistant: _____