



Site #: MBS 26 SN: 20 Date: 29th April 2024

EASTING: 496 854 NORTHING: 650 2153

nT: _____ LOCAL START TIME: 13:00
HH:MM


BATTERY

No Load: 13.15

w/ Solar panel: 13.25 cloudy

LEMI: 13.7

DIPOLES	E _x	E _y
Length (m)	<u>98</u>	<u>100</u>
kΩ	<u>0.05</u>	<u>0.1</u>
DC (mV)	<u>5.3</u>	<u>0.1</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.05</u>	<u>0.6</u>
S	<u>48</u>	<u>0.05</u>	<u>4.7</u>
E	<u>50</u>	<u>0.07</u>	<u>1.0</u>
W	<u>50</u>	<u>0.05</u>	<u>1.2</u>

Technician: Shane Assistant: Cory

LOCAL DATE: 01/06/24

LOCAL TIME: 1435

DIPOLES	Ex	E _y
kΩ	<u>12.9</u>	<u>0.03</u>
mV _{DC}	<u>-</u>	<u>0.9</u>

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: _____ Assistant: _____