

RETRIEVAL SHEET

Site #: M8T19 SN: 22 Box 22 Date: 20/4/14

EASTING: 234786 NORTHING: 6455618


nT: - 23 LOCAL START TIME: 13:15 HH:MM

BATTERY

No Load: 13.66
w/ Solar panel: 13.1

LEMI: _____

DIPOL	Ex	Ey
Length (m)	100	100
kΩ	5.0	3.0
DC (mV)	14.8	16.7



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	50	8.0	47.4
S	50	6.5	43.3
E	50	6.5	48.8
W	50	6.5	52.1

Technician: ZB Assistant: NE, CD, LD

admin2@m-geo.com.au

LOCAL DATE: 07/06/24

LOCAL TIME: 1050

DIPOL	Ex	Ey
kΩ	1.0	1.0
mV _{dc}	134.3	22.4

BATTERY

No Load: 3.49

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes:

E3 = WEST
E4 = EAST

Technician: NE Assistant: RS

Office: +61 (0)8 9371 7957