

Site #: MBT 23 SN: 60 box 60 Date: 21/4/24

EASTING: 645864 NORTHING: 0387617
nT: +70 LOCAL START TIME: 8.15
HH:MM


BATTERY

No Load: 11.74

w/ Solar panel: _____

LEMI: 12.25

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.4</u>	<u>0.5</u>
DC (mV)	<u>0.1</u>	<u>1.1</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>	<u>0.5</u>	<u>1.8</u>
S	<u>50</u>	<u>0.5</u>	<u>3.0</u>
E	<u>50</u>	<u>0.4</u>	<u>0.1</u>
W	<u>50</u>	<u>0.5</u>	<u>0.6</u>

Technician: ZB Assistant: LD, CD, NE

admin2@m-geo.com.au

LOCAL DATE: 31/05/24
LOCAL TIME: 0940

DIPOLES	E _x	E _y
kΩ	<u>0.002</u>	<u>0.04</u>
mV _{DC}	<u>2.9</u>	<u>1.7</u>

BATTERY

No Load: 14.62

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: _____ Assistant: _____

Office: +61 (0)8 9371 7957