


 Site #: MBU19 SN: 21 Date: 20/4/24

 EASTING: 6411383 NORTHING: 237018


 nT: +21 LOCAL START TIME: 10:04
HH:MM

BATTERY

No Load: 13.10w/ Solar panel: 15.5

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	1.0	1.7
DC (mV)	8.5	19.5



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N C ₁	50	1.0	11.4
S C ₂	50	1.0	7.3
E C ₁	50	1.1	22.2
W C ₂	50	1.3	9.2

 Technician: ZB Assistant: NE, CD, LD
LOCAL DATE: 04/06/24

LOCAL TIME: _____

DIPOLES	E _x	E _y
kΩ	1.2	1.7
mV _{DC}	19.4	14.4

BATTERY

No Load: FLAT

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Only 16 days of data.

Technician: _____ Assistant: _____