


Site #: MB021 SN: 028 Date: 15/3/21

EASTING: 6413292 NORTHING: 308844
nT: +27.3 LOCAL START TIME: 11.51
HH:MM

BATTERY

No Load: 12.62
w/ Solar panel: 12.8494
LEMI: 12.55 (overcast)

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	1.4	1.8
DC (mV)	1.6	6.0



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

C, N, L, L, R, L

RETRIEVAL SHEET

LOCAL DATE: 16.04.2024
LOCAL TIME: -

DIPOLES	E _x	E _y
kΩ	1.6	2.0
mV _{DC}	4.7	3.5

BATTERY

No Load: -

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	/				
Mag	/				
E _x	/				
E _y	/				
Central	/				

Notes:

Technician: ZB

Assistant: _____