

Site #: MBU22 SN: 58 Date: 17/4/24 - correct date

LOCAL DATE: 03/06/24

LOCAL TIME: 0835

EASTING: 646513 NORTHING: 0346762

nT: +30 LOCAL START TIME: 14.54

HH:MM


BATTERY

No Load: 13.31

w/ Solar panel: 13.40

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	<u>97</u>	<u>100</u>
.kΩ	<u>0.1</u>	<u>0.1</u>
DC (mV)	<u>9</u>	<u>21.6</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N E1	<u>50 (C1)</u>	<u>0.8</u>	<u>12.9</u>
S E2	<u>47 (C2)</u>	<u>1.4</u>	<u>26</u>
E E3	<u>50 (C1)</u>	<u>1.6</u>	<u>24.3</u>
W E4	<u>50 (C2)</u>	<u>1.8</u>	<u>10.1</u>

BATTERY

No Load: 5.3

solar panel not charging

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	☒				
Mag	☒				
E _x	☒				
E _y	☒				
Central	☒				

Notes:

Technician: ZB

Assistant: CD

Technician: _____

Assistant: _____