

Site #: MBu23 SN: 59 Date: 12/4/24 - wrong data on Lem

EASTING: 6414051 NORTHING: 0384728
nT: +51 LOCAL START TIME: 15:26
HH:MM


BATTERY

No Load: 12.65

w/ Solar panel: 12.7

LEMI: 12.66

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.2	0.2
DC (mV)	4.3	0.6



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: ZB Assistant: CO/LD

LOCAL DATE: 30/05/24
LOCAL TIME: 15:15

DIPOLES	E _x	E _y
kΩ	0.36	6.2
mV _{DC}	3.4	26.1

BATTERY

No Load: 14.6

CABLE STATUS (inspect cable prior to packing up site)
Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: Assistant: