

Site #: MB025

SN: Box 51 sn 181

Date: 12/4/24

EASTING: 6412916

NORTHING: 460858

nT: -58

LOCAL START TIME: 9:39

HH:MM


BATTERY

No Load: 13.1

w/ Solar panel: 13.28

LEMI: 14.29

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.3
DC (mV)	2.9	14.7



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: ZB

Assistant: CD, LD

admin2@m-geo.com.au

LOCAL DATE: 03/06/24

LOCAL TIME: 1400

DIPOLES	E _x	E _y
kΩ	26.2	1.0
mV _{DC}	0.1	9.5

BATTERY

No Load: 14.59

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician:

Assistant:

Office: +61 (0)8 9371 791