

Site #: MBV19 SN: 62 Date: 15/3/24


EASTING: 6367748 NORTHING: 237324

NT: +49.39 LOCAL START TIME: 8.50 HH:MM

**BATTERY**

No Load: 12.56  
w/ Solar panel: 12.65 (current)  
LEM: 12.74

| DIPOL      | Ex  | Ey  |
|------------|-----|-----|
| Length (m) | 100 | 100 |
| kΩ         | 2.6 | 2.6 |
| DC (mV)    | 10  | 4.6 |



| ELECTRODES | DISTANCE TO RX | kΩ to GND | mV <sub>DC</sub> to GND |
|------------|----------------|-----------|-------------------------|
| GND        |                |           |                         |
| N          | 50             |           |                         |
| S          | 50             |           |                         |
| E          | 50             |           |                         |
| W          | 50             |           |                         |

N.L. C.D. Assistant: Luke, Rezq, Louis

LOCAL DATE: 16-04-2024  
LOCAL TIME:

| DIPOL            | Ex  | Ey  |
|------------------|-----|-----|
| kΩ               | 2.0 | 1.8 |
| mV <sub>DC</sub> | 4.4 | 0.8 |

**BATTERY**

No Load: -

**CABLE STATUS (inspect cable prior to packing up site)**

Good: No changes  
Minor: few nibbles, minor damage shouldn't affect data  
Major: casing is damaged, internal wire is damaged  
Extreme: cord chewed through or connector missing

| Please tick | Good | Minor | Major | Extreme | Notes |
|-------------|------|-------|-------|---------|-------|
| Solar Panel | ✓    |       |       |         |       |
| Mag         | ✓    |       |       |         |       |
| Ex          | ✓    |       |       |         |       |
| Ey          | ✓    |       |       |         |       |
| Central     | ✓    |       |       |         |       |

Notes:

Technician: ZB

Assistant:

Office: +61