

Site #: MBV20 SN: 158 Box 61 Date: 19/04

EASTING: 272268 NORTHING: 6371143

nT: +39 LOCAL START TIME: 11.02

HH:MM


BATTERY

No Load: _____

w/ Solar panel: 12.68

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	5.0	5.0
DC (mV)	43.6	59.2



ELECTRODES	DISTANCE TO Rx		kΩ to GND	mV _{DC} to GND
GND				
N	50	E1	5.2.2 C1	35
S	50	E2	5.5 C2	42.5
E	50	E3	5.5 C1	39.1
W	50	EA	2.4 C2	54.3

Technician: ZB

Assistant: NE, LD

admin2@m-geo.com.au

LOCAL DATE: 04/06/24

LOCAL TIME: 1047

DIPOLES	E _x	E _y
kΩ	1	1.3
mV _{DC}	54.5	15.6

BATTERY

No Load: 14.5

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

No data recorded for the 24hr periods on the following dates;
24/05, 26/05

Technician: _____

Assistant: _____

Office: +61 (0)8 9371 7957