

Site #: MBV21 SN: 28 box 28 Date: 19/4

EASTING: 311 794 NORTHING: 6369058

nT: -62.3 LOCAL START TIME: 14:30
HH:MM


BATTERY

No Load: 12.9

w/ Solar panel: _____

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
k Ω	<u>0.2</u>	<u>0.3</u>
DC (mV)	<u>22.3</u>	<u>20.5</u>



ELECTRODES	DISTANCE TO Rx	k Ω to GND	mV _{DC} to GND
GND			
N E1	<u>50</u>	<u>0.2</u>	<u>50.7</u>
S E2	<u>50</u>	<u>0.2</u>	<u>11.5</u>
E E3	<u>50</u>	<u>0.15</u>	<u>27.6</u>
W E4	<u>50</u>	<u>0.2</u>	<u>11.1</u>

Technician: ZB Assistant: NE, LD

LOCAL DATE: 04/06/24

LOCAL TIME: 0845

DIPOLES	E _x	E _y
k Ω	<u>1.0</u>	<u>0.14</u>
mV _{DC}	<u>-</u>	<u>17.2</u>

BATTERY

No Load: 13.4

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	<u>X</u>				
Mag	<u>X</u>				
E _x	<u>X</u>				
E _y	<u>X</u>				
Central	<u>X</u>				

Notes:

Technician: _____

Assistant: _____