

Site #: MBV22 SN: No 178 Date: 3/3/24

EASTING: 6370039 NORTHING: 351627

nT: -14.5 LOCAL START TIME: 14:44

HH:MM


BATTERY

No Load: 12.92

w/ Solar panel: 13.20

LEMI: 13.39

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.8
DC (mV)	<u>32</u> 60	21.70



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: Z.B Assistant: N.L, C.D

RETRIEVAL SHEET

REPEAT

LOCAL DATE: 03/06/24

LOCAL TIME: 1047

DIPOLES	E _x	E _y
kΩ	0.03	1.14
mV _{DC}	0.5	51.4

BATTERY

No Load: 4.3
solar panel didn't charge

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes: 2 centre pots

REPEAT
Positions
E1 = West
E2 = East
E3 = North
E4 = South

Technician: _____ Assistant: _____