


Site #: MBV23 SN: 161 (Box 21) Date: 03/03/24EASTING: 6373674 NORTHING: 0386732nT: +3.0 LOCAL START TIME: 10:46 am
HH:MM

BATTERY

No Load: 12.69w/ Solar panel: 12.76LEMI: 12.81

	E _x	E _y
Length (m)	100	100
kΩ	0.2	0.4
DC (mV)	20.9	31.3



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: Z.BAssistant: N.L, C.DLOCAL DATE: 14-04-2024LOCAL TIME: 08:04

DIPOLES	E _x	E _y
kΩ	1.4	3.5
mV _{DC}	28.0	27.9

unstable

BATTERY

No Load: 13.68

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

Technician: Z.BAssistant: LD