

Site #: MBV 25 SN: No 173 (Box 58) Date: 11/13/24


 EASTING: 6371157 NORTHING: 461975

 nT: -3.40 LOCAL START TIME: 14:34 PM
HH:MM

BATTERY

No Load: 13.06w/ Solar panel: 13.4LEMI: 13.71

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.03</u>	<u>0.04</u>
DC (mV)	<u>6.9</u>	<u>0.2</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>		
S	<u>50</u>		
E	<u>50</u>		
W	<u>50</u>		

LOCAL DATE: 15.04.2024

LOCAL TIME: _____

DIPOLES	E _x	E _y
kΩ	<u>0.1</u>	<u>0.1</u>
mV _{DC}	<u>0.1</u>	<u>0.1</u>

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	☒				
Mag	☒				
E _x	☒				
E _y	☒				
Central	☒				

Notes:

Technician: ZB

Assistant: _____