

Site #: MBV25 SN: No 172 (Box 58) Date: 11/03/24

EASTING: 6321157 NORTHING: 461925

NT: -3.40 LOCAL START TIME: 14:54 PM HH:MM


BATTERY

No Load: 13.06

w/ Solar panel: 13.4

LEMI: 13.71

DIPOL	E _x	E _y
Length (m)	100	100
kΩ	0.03	0.04
DC (mV)	6.9	0.2



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{dc} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: Z.b Assistant: N.L, Luk

admin2@m-geo.com.au

LOCAL DATE: LOCAL TIME:

DIPOL	E _x	E _y
kΩ		
mV _{dc}		

BATTERY

No Load:

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes:

Technician: Assistant:

Office: +61 (0)8 9371 7957