

Site #: MBW19

SN: No. 156

Date: 4/3/24

EASTING: 6328268

NORTHING: 0241921

nT: -30.5

LOCAL START TIME: 15:07

HH:MM


BATTERY

No Load: 12.8

w/ Solar panel: 14.1

LEMI: 14.6

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.47	0.10
DC (mV)	287	3.4



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE:

LOCAL TIME:

DIPOLES	Ex	Ey
kΩ		
mV _{DC}		

BATTERY

No Load:

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes:

Technician: Z.B

Assistant: N.L, C.D

Technician:

Assistant: