

Site #: MBW/22R SN: Same as previous Date: 11/4/24

EASTING: same as previous NORTHING: same as previous
nT: -58 LOCAL START TIME: 14:39 HH:MM

BATTERY	
No Load:	13.2
w/ Solar panel:	13.9
LEMI:	13.68

Same as previous

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.2	0.2
DC (mV)	7.8	9.2

ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: ZB Assistant: CD, LD
admin2@m-geo.com.au

LOCAL DATE: 30/05/24
LOCAL TIME: 10:30

DIPOLES	Ex	E _y
kΩ	unstable	unstable
mV _{DC}		

BATTERY
No Load: 13.94

CABLE STATUS (inspect cable prior to packing up site)
Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:
11/4/24
E line checked
pots watered
mag relined

Technician: Assistant: Office: +61 (0)8 9371 7957