

Site #: MBN23 SN: NO 165 (box 18) Date: 7/3/24


EASTING: 6324625 NORTHING: 0385859

NT: -8.2 LOCAL START TIME: 15:40 HH:MM

BATTERY

No Load: 13.13
w/ Solar panel: 13.2
LEMI: 13.49

DIPOLLES	E _x	E _y
Length (m)	93	100
kΩ	0.2	0.2
DC (mV)	4.5	2.1



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{dc} to GND
GND			
N	42.5		
S	50		
E	50		
W	50		

Technician: _____ Assistant: _____
admin2@m-geo.com.au

LOCAL DATE: 11/4/24
LOCAL TIME: 12:07

DIPOLLES	E _x	E _y
kΩ	2	2
mV _{dc}	5.2	1.4

BATTERY

No Load: 14.58

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

Technician: 28 Assistant: CD, LD
Office: +61 (0)8 9371 7