

Site #: MBW24 SN: No 160 Date: 7/3/24

EASTING: 6324030 NORTHING: 0421969

nT: -88.8 LOCAL START TIME: 12.26 HH:MM


BATTERY

No Load: 12.8

w/ Solar panel: 13.08

LEMI: 12.99

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.142	0.1
DC (mV)	1.4	4.7



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{bc} to GND
GND			
N	50	0.1	
S	50	0.1	
E	50	0.1	
W	50	0.1	

LOCAL DATE: _____

LOCAL TIME: _____

No Load: _____

DIPOLES	E _x	E _y
kΩ		
mV _{bc}		

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes: _____

Technician: ZB Assistant: BC, CD

admin2@m-geo.com.au

Technician: _____ Assistant: _____

Office _____