

Site #: MBX 20 SN: No 191 (Box 51) Date: 06/03/24

EASTING: 627635E NORTHING: 298913


NT: +14.41 LOCAL START TIME: 17:10 PM HH:MM

BATTERY

No Load: 12.56
w/ Solar panel: 12.59 (VINT NIVE)
LEMI: 12.50

TRACK 70m

DIPOLLES	E _x	E _y
Length (m)	100	100
kΩ	0.6	2.1
DC (mV)	19.34.24	7.7 34.14



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 9/4/24
LOCAL TIME: 1.51

DIPOLLES	E _x	E _y
kΩ	2.1	mΩ
mV _{DC}	26.9	8.9 unstable

BATTERY

No Load: 14.3

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓		✓		chewed in half - repaired
Central	✓				

Notes:

E_y - mv after repair 14.2
- kΩ after repair 1.2

Technician: 2.3 Assistant: N.L., C.D

Technician: ZB Assistant: L.D., C.D