

Site #: MBX21 SN: Box 35 sn-170 Date: 10/4/24

 EASTING: 6292821 NORTHING: 0313903

 nT: - 5.73 LOCAL START TIME: 13.44
HH:MM


BATTERY

 No Load: 13.1

 w/ Solar panel: 15.73

 LEMI: 15.6

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.1
DC (mV)	2.6	1.4

 tall dense
shrub


ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

 Technician: ZB Assistant: LD, CD

 LOCAL DATE: 29/05/24

 LOCAL TIME: 15:00

DIPOLES	E _x	E _y
kΩ	no read	0.4
mV _{DC}	no read	1.1

BATTERY

 No Load: FLAT
turned off on 24/05/24

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	x				
Mag	x				
E _x				x	south line completely chewed through
E _y				x	west line chewed but not broken
Central					

Notes:

both lines were chewed at the box where cable goes in

Technician: _____

Assistant: _____