

Site #: 14 M6X22 SN: 153 Date: 02/03/24

EASTING: 6283379 NORTHING: 0356886

NT: - 38.60 LOCAL START TIME: 15.36

HH:MM


BATTERY

No Load: 13.1

w/ Solar panel: 13.3 (overcast)

LEMI: _____

DIPOLLES	E _x	E _y
Length (m)	100	100
kΩ	1	2.4
DC (mV)	12.8 29.4	13.5



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: Z.B Assistant: C.O, N.L

admin2@m-geo.com.au

LOCAL DATE: ~~02/03/24~~ 10/4/24

LOCAL TIME: ~~15.36~~ 16.04

DIPOLLES	E _x	E _y
kΩ	1.5 0.5	1.1
mV _{dc}	8.3	3.5

BATTERY

No Load: 14.6

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

Technician: _____ Assistant: _____

Office: _____