

Site #: MXB24 SN: 53 Date: 1/3/24

EASTING: 6281864 NORTHING: 049214

NT: 53.26 LOCAL START TIME: 16 45 HH:MM


BATTERY

No Load: 13.1

w/ Solar panel: 13.9

LEMI: 13.8

DIPOL	Ex	Ey
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.1</u>	<u>1.0</u>
DC (mV)	<u>36.1</u>	<u>5.3</u>



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N			
S			
E			
W			

LOCAL DATE: _____
LOCAL TIME: _____

DIPOL	Ex	Ey
kΩ		
mV _{dc}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
Ex					
Ey					
Central					

Notes:

Technician: ZB, SB Assistant: CD, NL
admin2@m-geo.com.au

Technician: _____ Assistant: _____