

Site #: MBX26

SN: Box 1 SN-189

Date: 9/3/24

EASTING: 6292062

NORTHING: 499046

nT: -5.7

LOCAL START TIME: 11.29


HH:MM

BATTERY

No Load: 13.27

w/ Solar panel: 15

LEMI: 13.9



DIPOL	E _x	E _y
Length (m)	100	100
kΩ	0.2	0.2
DC (mV)	5.3	0.4

ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 15.04.2024

LOCAL TIME: 1440

DIPOL	E _x	E _y
kΩ	0.1	0.1
mV _{DC}	0.9	0.2

BATTERY

No Load: 12.4

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

N/E

N/E

Assistant: CD LD