


Site #: MB419 SN: LP9 Date: 9/4/24 *date is coll*

EASTING: 6244926 NORTHING: 233182
nT: -22 LOCAL START TIME: 9.23
HH:MM

BATTERY

No Load: 12.9
w/ Solar panel: 14.2
LEMI: 14.1

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>1.2</u>	<u>0.809</u>
DC (mV)	<u>27.4</u>	<u>0.5</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>50</u>		
S	<u>50</u>		
E	<u>50</u>		
W	<u>50</u>		

LOCAL DATE: 29/05/24
LOCAL TIME: 11:45

DIPOLES	Ex	E _y
kΩ	unstable	
mV _{DC}	unstable	

BATTERY

No Load: 14.5 on solar

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	x				
Mag	x				
E _x	x				
E _y	x				
Central	x				

Notes:

Technician: ZB Assistant: LD, CO

Technician: Assistant: