

Site #: MBY 21 SN: No 192 Date: 6/3/24

EASTING: 6256943 NORTHING: 0310270

NT: -54.4 LOCAL START TIME: 13.35 HH:MM


BATTERY

No Load: 13.2

w/ Solar panel: 15.04

LEMI: 13.77

DIPOLLES	E _x	E _y
Length (m)	100	100
kΩ	0.7	0.5
DC (mV)	8.2	15



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 10.04.24
LOCAL TIME: 07.52

DIPOLLES	E _x	E _y
kΩ	0.9	5.5
mV _{DC}	<u>2.04</u>	264.3

BATTERY

No Load: 5.3

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes: mag cable chewed.

Technician: ZB Assistant: CD, NL

admin2@m-geo.com.au

Technician: ZB

Assistant: CD, LD

Office: +61 (0)ur