


Site #: MBY24 SN: 167 Date: 01/03/24EASTING: 6247710 NORTHING: 0426071RT: 65 LOCAL START TIME: ~~14:00~~ 14:00
HH:MM

BATTERY

No Load: 13.1w/ Solar panel: 12.92LEMI: 12.89

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	26	20
DC (mV)	92.1	95



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N			<u>31</u>
S			<u>60</u>
E			<u>70</u>
W			<u>24.4</u>

Technician: ZB, SBAssistant: CD, NLLOCAL DATE: 15.04.2024LOCAL TIME: 07:10

DIPOLES	Ex	E _y
kΩ	1.6	1.4
mV _{DC}	88.8	58.5

unstable

BATTERY

No Load: flat

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	☒				
Mag	☒				
E _x	☒				
E _y	☒				
Central	☒				

Notes:

Technician: NEAssistant: CD