AusLAMP WA DEPLOYMENT SHEET

MOOMBARRIGA GEOSCIENCE

Site #: MBR24 SN: _____ Date: 2/5/24

EASTING: 431577 NORTHING: 6543804

nT: _____ LOCAL START TIME: 1100

HH:MM

BATTERY

No Load: 12.9

w/ Solar panel: 15.1

LEMI: _____

DIPOLES	E_x	E_y
Length (m)	100	100
kΩ	0.1	0.2
DC (mV)	~~35.8~~	~~39.6~~



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV_{DC} to GND
GND			
N	50	0.1	~~41.2~~
S	50	0.1	~~5.2~~
E	50	0.2	~~0.6~~
W	50	0.1	~~38.9~~

Technician: SE Assistant: CC

admin2@m-geo.com.au

RETRIEVAL SHEET

MOOMBARRIGA GEOSCIENCE

LOCAL DATE: 06/06/24

LOCAL TIME: 1311

DIPOLES	Ex	E_y
kΩ	0.4	1.0
mV_{DC}	39.4	34.6

BATTERY

No Load: 13.65

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	x				
Mag	x				
E_x	x				
E_y	x				
Central	x				

Notes:

Technician: _____ Assistant: _____

Office: +61 (0)8 9371 7957