

Site #: MBS20 SN: 22 Date: 14/3/24

EASTING: 6501305 NORTHING: 0273015

nT: +10.95 LOCAL START TIME: 8.41
HH:MM

BATTERY


No Load: 12.62

w/ Solar panel: 12.75 (overcast)

LEMI: 12.61

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.35	0.15
DC (mV)	0.5	26.9

low dense
shrub



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 16-04-2024

LOCAL TIME: -

DIPOLES	E _x	E _y
kΩ	1.4	0.7
mV _{DC}	21.5	12.8

BATTERY

No Load: -

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	☒				
Mag	☒				
E _x	☒				
E _y	☒				
Central	☒				

Notes:

Technician: ZB

Assistant: Louis, CD

Technician: ZB

Assistant:

Office: +61 (0)8