

AusLAMP WA DEPLOYMENT SHEET



Site #: MBS23 SN: 62 Date: 18/4/24

EASTING: 369879 NORTHING: 6487342

nT: +65.97 LOCAL START TIME: HH:MM


BATTERY

No Load: _____

w/ Solar panel: 14.33

LEMI: _____

DIPOLES	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.2</u>	<u>0.1</u>
DC (mV)	<u>3.3</u>	<u>1.3</u>



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	<u>40</u>	<u>0.5</u>	<u>4.9</u>
S	<u>40</u>	<u>0.05</u>	<u>1.6</u>
E	<u>40</u>	<u>0.5</u>	<u>1.0</u>
W	<u>40</u>	<u>0.07</u>	<u>3.0</u>

RETRIEVAL SHEET



LOCAL DATE: 02/06/24

LOCAL TIME: 1400

DIPOLES	E _x	E _y
kΩ	<u>1.0</u>	<u>1.0</u>
mV _{DC}	<u>1.1</u>	<u>1.0</u>

BATTERY

No Load: 13.0

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: _____

Assistant: _____

Technician: ZB Assistant: NE, CD, CD

admin2@m-geo.com.au

Office: +61 (0)8 9371 7957