

AusLAMP WA DEPLOYMENT SHEET



RETRIEVAL SHEET




Site #: MB524 SN: B0x27 SN:191 Date: 18/04/2024 ^{correct}

EASTING: 6503473 NORTHING: 427452
nT: -77.57 LOCAL START TIME: 10:36
HH:MM

BATTERY

No Load: 13.25
w/ Solar panel: 14.5
LEMI: _____

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.1
DC (mV)	10.9	3.5



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
E ₁ N C ₁	50	0.1	21.7
E ₂ S C ₂	50	0.1	4.4
E ₃ E C ₁	50	0.1	27.3
E ₄ W C ₂	50	0.1	17.5

LOCAL DATE: 02/06/24
LOCAL TIME: _____

DIPOLES	E _x	E _y
kΩ		
mV _{DC}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel			X		
Mag				X	
E _x	X				
E _y		X			
Central				X	

Notes:

cows chewed lines at the box. box had been pushed around and cable pulled out of the ground

Technician: Z.B. N.E Assistant: E.O. L.O

Technician: _____

Assistant: _____