

Site #: MST20 SN: 60 Date: 14/3/24 *Levin 2024*

EASTING: 6456720 NORTHING: 274058

NT: -74.70 LOCAL START TIME: 11.08 HH:MM


BATTERY

No Load: 12.56

w/ Solar panel: 12.66 (overcast)

LEMI: 12.88

DIPOLLES	E _x	E _y
Length (m)	100	100
kΩ	0.2	0.4
DC (mV)	9.9	9.3



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 16.04.2024
LOCAL TIME: -

DIPOLLES	E _x	E _y
kΩ	0.2	0.4
mV _{dc}	6.2	7.3

BATTERY

No Load: -

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

Technician: ZB

Assistant: _____