



Site #: MBT24 SN: 61 Date: 12/4/24

EASTING: 6459256 NORTHING: 0424794
nT: +53 LOCAL START TIME: 15.12
HH:MM

BATTERY

No Load: 12.9
w/ Solar panel: 13.8
LEMI: 14.06

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.1
DC (mV)	5.6	2.06

low/med
dense shrub



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50 (c1)	0.1	6.3
S	50 (c2)	0.1	0.8
E	50 (c1)	0.1	0.1/2.1
W	50 (c2)	0.1	0.5

Technician: ZB

Assistant: CD, LD

admin2@m-geo.com.au

LOCAL DATE: 31/05/24
LOCAL TIME: 1130

DIPOLES	Ex	E _y
kΩ		0.26
mV _{DC}	19.4	0.9

BATTERY

No Load: 14.1

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician: _____

Assistant: _____

Phone: +61 (0)8 9371 7957