

Site #: M8T26 SN: 55 Date: 13/4/24 *wrong date on Lemi*

EASTING: 6474190 NORTHING: 050522

nT: +5 LOCAL START TIME: 11:24
HH:MM


BATTERY

No Load: 13.2

w/ Solar panel: 14.4

LEMI: 14.31

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.4	0.3
DC (mV)	6.2	1.1



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50	0.4 (C1)	8.1
S	50	0.5 (C2)	29.7
E	50	0.2 (C1)	6.4
W	50	0.5 (C2)	27.9

LOCAL DATE: 31/05/24

LOCAL TIME: 1620

DIPOLES	E _x	E _y
kΩ	-	0.4
mV _{DC}	5.1	4.9

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	x				
Mag	x				
E _x	x				
E _y	x				
Central	x				

Notes:

Technician: ZB

Assistant: LD, CD

Technician: _____

Assistant: _____