

Site #: MBU24

SN: Box 28 SN165

Date: 12-04-2024

EASTING: 6415090

NORTHING: 432004

nT: +7

LOCAL START TIME: 12:04

HH:MM

BATTERY

No Load: 13.37

w/ Solar panel: 13.34

LEMI: 13.34 overcast

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.1
DC (mV)	0.2	8.8

ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50m		
S	50m		
E	50m		
W	50m		

Technician: ZB

Assistant: LD, CD

LOCAL DATE: 03/06/24

LOCAL TIME: 1500

DIPOLES	E _x	E _y
kΩ	0.6	1.0
mV _{DC}	14	22.6 - not stable

BATTERY

No Load: 14.67

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	X				
Mag	X				
E _x	X				
E _y	X				
Central	X				

Notes:

Technician:

Assistant: