

Site #: MB4 26 SN: No 029 Date: 13/3/24

EASTING: 6415104 NORTHING: 499955

 nT: -62.20 LOCAL START TIME: 15:09 PM
HH:MM


BATTERY

No Load: 12.57

w/ Solar panel: 12.64

LEMI: 12.56

DIPOLES	E_x	E_y
Length (m)	100	100
k Ω	0.05	0.03
DC (mV)	6.5	2.4



ELECTRODES	DISTANCE TO Rx	k Ω to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 15.04.2024

LOCAL TIME:

DIPOLES	E_x	E_y
k Ω	—	—
mV _{DC}	—	—

BATTERY

No Load:

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	/				
Mag	/				
E_x	/				
E_y	/				
Central	/				

Notes:

Technician: N.L

Assistant: Reza, Lase

Technician: 28

Assistant: