

CAMP WA DEPLOYMENT SHEET



Site #: MBU 26 SN: no 032 (Box) Date: 12/3/24


EASTING: 6372184 NORTHING: 500214

NT: +70.2 LOCAL START TIME: 00:53 am HH:MM

BATTERY

No Load: 12.69
w/ Solar panel: 12.86
LEMI: 12.82

DIPOLLES	Ex	Ey
Length (m)	100	100
kΩ	0.35	0.40
DC (mV)	1.9	0.2



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	60		
S	50		
E	50		
W	50		

LOCAL DATE: _____

LOCAL TIME: _____

DIPOLLES	Ex	Ey
kΩ		
mV _{dc}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

- Good: No changes
- Minor: few ripples, minor damage shouldn't affect data
- Major: casing is damaged, internal wire is damaged
- Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
Ex					
Ey					
Central					

Notes: _____

Technician: _____

Assistant: _____