

Site #: MBW20 SN: No 191 Date: 4/3/24


EASTING: 6321157 NORTHING: 0278009

NT: +1.43 LOCAL START TIME: 12:14 PM
HH:MM

BATTERY

No Load: 13.4
w/ Solar panel: 14.00
LEMI: 13.94

DIPOLS	E _x	E _y
Length (m)	120	100
kΩ	0.5	0.6
DC (mV)	14.7	9.4



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	50		
S	30		
E	50		
W	50		

Technician: Z.B Assistant: N.L, C.D

LOCAL DATE: _____
LOCAL TIME: _____

DIPOLS	E _x	E _y
kΩ		
mV _{dc}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes: