


Site #: MBW21 SN: Box 22 sn-182 Date: 8/3/24

EASTING: 6329270 NORTHING: 318684
nT: -62 LOCAL START TIME: 10.48
HH:MM

BATTERY

No Load: 13.13
w/ Solar panel: 13.30 (overcast)
LEMI: 13.55

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	2.2	0.05
DC (mV)	10.4	10.6



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: _____
LOCAL TIME: _____

DIPOLES	E _x	E _y
kΩ		
mV _{DC}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes:

Technician: ZB Assistant: CD, BC

Technician: _____ Assistant: _____