

LOCAL DATE: 15/4/24
LOCAL TIME: _____

DIPOLES	Ex	Ey
kΩ	2.7	1.6
mV _{DC}	10.8	9

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)


Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes: _____

Technician: _____ Assistant: _____

Site #: MBN26 SN: SN026 Box 26 Date: 11/3/24
EASTING: 632933 NORTHING: 500588
nT: +50.00 LOCAL START TIME: 11.00 AM
HH:MM



BATTERY

No Load: 12.60
w/ Solar panel: 12.61
LEMI: _____

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	2.4	1.5
DC (mV)	24.3	24.4

ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: Z.B Assistant: 6 N.L.C.D.