AusLAMP WA DEPLOYMENT SHEET

MOOMBARRIGA GEOSCIENCE

Site #: MBX19 SN: Box 35 sn 170 Date: 9/3/24

EASTING: 6279548 NORTHING: 7245537

nT: +61.5 LOCAL START TIME: 12:08
HH:MM

BATTERY

No Load: 13.06

w/ Solar panel: 13.24 (over cast)

LEMI: 13.25

DIPOLES	E_x	E_y
Length (m)	100	100
kΩ	0.2	0.2
DC (mV)	6.6	5.1



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV_{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

Technician: ZB Assistant: CD, BC

RETRIEVAL SHEET

MOOMBARRIGA GEOSCIENCE

LOCAL DATE: 9/4/24

LOCAL TIME: 11:15

DIPOLES	Ex	E_y
kΩ	0.2	0.1
mV_{DC}	0.7	3.9

BATTERY

No Load:

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E_x	✓				
E_y	✓				
Central	✓				

Notes:

Technician: ZB Assistant: LD, CP

Office: +61 (0)8 9371 7957

Scanned with CamScanner