


Site #: MBX23 SN: Box 34 sm 153 Date: 11/4/24 - correct on box

EASTING: 6280843 NORTHING: 0387222
nT: +73 LOCAL START TIME: 11:10
HH:MM

BATTERY

No Load: 13.16
w/ Solar panel: 13.3
LEMI: 13.84

DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.4	1
DC (mV)	13 unstable	12 unstable



ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 30/05/24
LOCAL TIME: 08:30

DIPOLES	E _x	E _y
kΩ	not stable	not stable
mV _{DC}		

BATTERY

No Load: 13.8

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	x				
Mag	x				
E _x	x				
E _y	x				
Central	x				

Notes:

11/4/23

E lines having issues, changed pots several times

no evidence of cable damage

Technician: 28 Assistant: CD, LD

Technician: Assistant: