

RETRIEVAL SHEET

Site #: M6X W4410 25 SN: 166 Date: 2/3/24


EASTING: 6280399 NORTHING: 0463398

NT: -75 LOCAL START TIME: 11.18 HH:MM

BATTERY

No Load: 13.3
w/ Solar panel: 14.5
LEMI: 14.9

DIPOL	E _x	E _y
Length (m)	<u>100</u>	<u>100</u>
kΩ	<u>0.03</u>	<u>0.04</u>
DC (mV)	<u>14.5</u>	<u>17.3</u>



ELECTRODES	DISTANCE TO RX	kΩ to GND	mV _{dc} to GND
GND			
N	<u>50</u>	<u>-</u>	<u>-</u>
S	<u>50</u>	<u>-</u>	<u>-</u>
E	<u>50</u>	<u>-</u>	<u>-</u>
W	<u>50</u>	<u>-</u>	<u>-</u>

LOCAL DATE: _____
LOCAL TIME: _____

DIPOL	E _x	E _y
kΩ		
mV _{dc}		

BATTERY

No Load: _____

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes
Minor: few nibbles, minor damage shouldn't affect data
Major: casing is damaged, internal wire is damaged
Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel					
Mag					
E _x					
E _y					
Central					

Notes:

Notes:

Technician: ZJR Assistant: CD, NL

Technician: _____ Assistant: _____