

Site #: MBX27

SN: No 168 (Box 50)

Date: 5/3/24

EASTING: 6285596

NORTHING: 05293333

nT:

+ 73.1

LOCAL START TIME: 14.04

HH:MM

BATTERY

No Load:


12.62

w/ Solar panel:

12.72

LEMI:

12.86



DIPOLES	E _x	E _y
Length (m)	100	100
kΩ	0.1	0.1
DC (mV)	4.2	1.1

ELECTRODES	DISTANCE TO Rx	kΩ to GND	mV _{DC} to GND
GND			
N	50		
S	50		
E	50		
W	50		

LOCAL DATE: 15-04-2024

LOCAL TIME: 10.13

DIPOLES	E _x	E _y
kΩ	1.2	1.8
mV _{DC}	1.7	4.9

BATTERY

No Load:

13.65

CABLE STATUS (inspect cable prior to packing up site)

Good: No changes

Minor: few nibbles, minor damage shouldn't affect data

Major: casing is damaged, internal wire is damaged

Extreme: cord chewed through or connector missing

Please tick	Good	Minor	Major	Extreme	Notes
Solar Panel	✓				
Mag	✓				
E _x	✓				
E _y	✓				
Central	✓				

Notes:

Technician: ZB

Assistant: CD, NL

NE

Assistant: LD, CD